

Performing a reset

- 1. To unlock, press **Menu** for three seconds.
- 2. Press **Menu** once.



Move your finger clockwise around the scroll wheel until the bar is on COMMISSIONING. Then press OK







4. Move your finger clockwise around the scroll wheel again until the bar is on "RESET".

Then press **OK**.





Move your finger clockwise around the scroll wheel again until the bar is on "HEAT PUMP". Then press OK.



6. The display shows a "O".





7. Move your finger clockwise around the scroll wheel once again until a **"1"** is displayed. Then press **OK 4x times** (code 1000).





 \neg



8. The display shows **OFF**. Move your finger clockwise around the scroll wheel until **ON** is displayed.

Then press OK.







9. Press the "Menu" button until the start screen appears again.
Alternatively, leave the settings as they are. The display will switch back automatically after a while.

